

Company Name

Available in MaintSmart 4.1
December, 2013


OEE (Overall Equipment Effectiveness)

Print Date: 11:04:01AM

Start End Planned (min.) Down (min.) Availability Performance Quality OEE

Sacramento

Average OEE / Work Area




Data may be grouped by:

- 1.) Plant
- 2.) Equipment
- 3.) Process
- 4.) Line
- 5.) Work Area
- 6.) Schedule

Summary (not shown) is listed at the bottom of each group.

Bldg Compressor Room



Air Compressor #1

3/23/2013	11:43:08PM	3/24/2013	7:43:08AM	427	43	89.93%	83.64%	97.33%	73.21%
3/15/2013	2:04:37AM	3/15/2013	10:04:37AM	450	13	97.11%	73.50%	98.59%	70.37%
3/17/2013	12:04:37AM	3/17/2013	10:04:37AM	528	0	100.00%	63.13%	94.24%	59.49%
Average: - Air Compressor #1						95.68%	73.42%	96.72%	67.69%

Air Compressor #2


3/23/2013	11:43:08PM	3/24/2013	7:43:08AM	420	63	85.00%	89.97%	97.26%	74.38%
3/15/2013	2:04:37AM	3/15/2013	10:04:37AM	450	13	97.11%	73.50%	98.59%	70.37%
3/17/2013	12:04:37AM	3/17/2013	10:04:37AM	528	0	100.00%	63.13%	94.24%	59.49%
Average: - Air Compressor #2						94.04%	75.53%	96.70%	68.08%

Air Compressor #3

3/23/2013	11:44:08PM	3/24/2013	7:43:08AM	419	40	90.45%	87.95%	94.24%	74.97%
3/15/2013	2:04:37AM	3/15/2013	10:04:37AM	450	13	97.11%	73.50%	98.59%	70.37%

Start	End	Planned (min.)	Down (min.)	Availability	Performance	Quality	OEE
3/17/2013 12:04:37AM	3/17/2013 10:04:37AM	528	0	100.00%	63.13%	94.24%	59.49%
Average: - Air Compressor #3				95.85%	74.86%	95.69%	68.28%
Average: - Bldg Compressor Room				95.19%	74.61%	96.37%	68.02%

Bldg Refrigeration Room




York Chiller #1

4/15/2013 2:04:37AM	4/15/2013 10:04:37AM	420	26	93.81%	81.52%	88.84%	67.94%
3/15/2013 3:04:37AM	3/15/2013 10:04:37AM	360	37	89.72%	92.88%	94.44%	78.70%
3/17/2013 2:04:37AM	3/17/2013 10:04:37AM	408	10	97.55%	82.50%	96.98%	78.04%
Average: - York Chiller #1				93.69%	85.63%	93.42%	74.89%

York Chiller #2

4/15/2013 2:04:37AM	4/15/2013 10:04:37AM	420	56	86.67%	88.24%	92.37%	70.63%
3/15/2013 3:04:37AM	3/15/2013 10:04:37AM	360	37	89.72%	92.88%	94.44%	78.70%
3/17/2013 2:04:37AM	3/17/2013 10:04:37AM	408	12	97.06%	82.91%	99.26%	79.88%
Average: - York Chiller #2				91.15%	88.01%	95.36%	76.41%
Average: - Bldg Refrigeration Room				92.42%	86.82%	94.39%	75.65%

Bread Proofing



Start	End	Planned (min.)	Down (min.)	Availability	Performance	Quality	OEE
Bread Proofbox L1PB							
4/15/2013 2:04:37AM	4/15/2013 10:04:37AM	420	56	86.67%	88.24%	88.26%	67.50%
3/15/2013 3:04:37AM	3/15/2013 10:04:37AM	373	50	86.60%	99.44%	99.63%	85.79%
3/17/2013 2:54:37AM	3/17/2013 10:04:37AM	370	120	67.57%	97.95%	89.01%	58.91%
Average: - Bread Proofbox L1PB				80.28%	95.21%	92.30%	70.73%
Average: - Bread Proofing				80.28%	95.21%	92.30%	70.73%
Average: - Sacramento				91.78%	82.11%	95.03%	71.01%
Average:				91.78%	82.11%	95.03%	71.01%